'STRUCTURAL AUDIT REPORT'

"S.P. MANDALI's"

RAMNARAIN RUIA

AUTONOMOUS COLLEGE,

AT MATUNGA,

MUMBAI - 400 019.

V.V.JOSHI AND ASSOCIATES

Consulting Engineers
Mumbai



V. V. JOSHI AND ASSOCIATES CONSULTING ENGINEERS

5, Ishwar Bhavan, Liberty Garden Cross Road No.2, Malad (West), Mumbai - 400 064. Telefax: 2882 0966 • Email: vvjoshiasso@gmail.com

REF: 75/21 STRUCTURAL AUDIT REPORT FOR RUIA COLLEGE

DATE	16.03.202
	Sub.

Su		ORMA 'B'				
1000				STRUCTURAL AUDIT		
iva	ame of Consultant.			IH2OL.V.V		
_	ame Of Building	SP	MANDAL	I'S RAMNARAIN RUIA AUTONOMOUS SENIOR COLLEGE		
	T.S. No./Ward			CS NO 163/10 TO 179/10		
_	of Storey		PART E	SASEMENT+GROUND +3 FLOORS		
-	ar of Construction			1937		
-	er Department	EDUCATIONAL INSTITUTE				
6 M	ode Of Construction of existing bldg.					
	i) Foundation		WALL FOUNDATIONS			
-	ii) Floors			RCC FLOOR SLABS		
_	iii) Walls		BRICK WALL	S LOAD BEARING AND NON LOAD BEARING		
_	iv) Beams			RCC FLOOR BEAMS		
	v) Columns			RCC COLUMNS		
	vi) Roof		FLAT	RCC ROOF AND PITCHED ROOF		
7 His	story of Repairs done year -wise-			5000000		
-	Slab recasting		NOT REQUIRED NOT REQUIRED			
(b)	Column Jacketing					
	i) Structural Repairs			2010-11		
\perp	ii) Tenantable Repairs		AS AND WHEN REQUIRED			
	iii) Roof /Waterproofing			DONE		
	iv) Plumbing		,	AS AND WHEN REQUIRED		
	v) Additions/ Alterations if Any			MEZZANINES ADDED		
8 Dat	te of Inspection by Consultant			25th FEBRUARY 2021		
9 Cor	ndition of					
	i) Internal plaster			ОК		
i	ii) External plaster		ОК			
ii	ii) Plumbing		SOME LEAKAGES ARE THERE			
i	v) Drains lines/ chambers			σк		
0 a) [a) Doors & windows don't close		DOORS AND WINDOWS GET CLOSED			
b) (Columns & Steel exposed		NO COLUMNS CRACKS OBSERVED NO UNEVEN SETTELMENT NO FOUNDATION SETTELMENT OBSERVED NO SAGGING AND DEFLECTION			
c) S	ettlement uneven flooring gaps between and skirting &	floor				
d) F	Foundation settlement					
e) [Deflections/ sagging					
f) N	Major cracks in column/ beams		NO MAJOR CRACKS LEAKAGES ARE PRESENT OK OK			
g) S	Seepages/ Leakages					
h) 5	Staircase area/ column condition					
i) Li	ifts walls					
j) U	J.G. Tank		NO PROBLEM IN THIS AREA			
k) C	k) OHT/ Column condition		NO PROBLEM IN THIS AREA			
I) P	I) Parapet at terraces m) Chhajas n) Common areas o) Toilet blocks p) Terrace Water Proofing		OK SMALL CRACKS IN CHAJJAS			
m)						
				FOUND OK		
o) T			FOUND OK OK			
p) T						
2 Tes	Test carrired out on structure/ observations there of		ngs	Range as per IS Code		
ND			891.27	3500		
	b) Rebound Hammer Test (Avg. Rebound value		20.2	Fair		
	c) Half Cell Potential Test (Mv)		-288	50% corrosion		
	d) Carbonation Depth Test (mm)	.	24	10 to 13.5		
	e) Core Test (MPa)		15.63	77.02. 72.12		
	f) Chemical Analysis (pH,Cl,SO3)		250 mg/l	Not Less than 8, <0.6, > 400mg/l		
_	g) Loss of thickness of structural members (%					



V. V. JOSHI AND ASSOCIATES CONSULTING ENGINEERS

5, Ishwar Bhavan, Liberty Garden Cross Road No.2, Malad (West), Mumbai - 400 064. Telefax: 2882 0966 • Email: vvjoshiasso@gmail.com

L3	Distress Mapping Plan & Photograph with caption below about description of structural member and its location	ARE	ATTACHED WITH REPORT	
	Brief Description of repairs to be done	POLYMER MODIFIED MORTAR REPAIRS		
_	a) Water proofing		NOT NECESSARY	
$\overline{}$	b) External plaster		NOT NECESSARY	
	c) Structural repairs			
	i) Column jacketing	NOT NECESSARY		
	ii)Slab recasting	NOT NECESSARY		
	iii) RCC cover to be replaced	NOT NECESSARY		
0.00	iy) Beam recasting.	NOT NECESSARY		
	d) Partial Evacuation during repairs needed	NOT NECESSARY		
	e) Propping		NOT NECESSARY	
15	Conclusions Of Consultants	Observations	Key reason	
	i) Whether structure is Livable/ of wheather it is to be evacuated/ pulled Down.	STRUCTURAL IS LIVABLE		
	ii) Whether structure requires tenantable repairs/ major structural repairs & its time frame	REPAIRS REQD	MINOR TENANTABLE REPAIRS	
	iii) Whether Structure can be allowed to occupy during course of repairs	YES	YES	
	iv) Nature/ Methodology of repairs.		APPLY POLYMER MODIFIED MORTAR	
100	v)Wheather Structure requires immediate propping if so its propping plan/ methodology given	NO		
	vi) Whether other immediate safety measures required -what is specific recommendation	NIL		
	vii) Enhancement in life of structure after required repairs /frecuency of repairs required in extended life period			
	viii) projected repair cost/sq.ft			
	ix) projected reconstruction cost/sq.ft			
	x) specific remarks ,wheather building needs to be vacated/demolished/ repairable.			
	xi) whether structure in exetremely critical condition		CRITICAL CONDITION	
1	Critical Observation			
_	7 Classification of Bldg.	C3	Auditors Final conslusion	
		C 1	To be evacuated demolition immediately.	
		C2- A	To be evacuated and/or partial demolition requiring strctural repairs	
		C2-B	No eviction only structural repai	
		СЗ	No eviction needs repairs only	

Signature

Structural Auditor. JOSHI

Consulting Engineer M.C.G.M. Reg. No. STR/J/4



REF: 76/21 DATE: 16.03.2021

STRUCTURAL AUDIT REPORT FOR RUIA COLLEGE

PROFORMA	В				
Sub.		STRUCTURAL AUDIT			
Name of Consultant.		V.V.JOSHI			
1 Name Of Building	S P MANDALI	'S RAMNARAIN RUIA AUTONOMOU			
A STATE OF THE PROPERTY OF THE		JUNIC COLLEGE CS NO 163/10 TO 179/10 GROUND+4 1992			
2 C.T.S. No./Ward	(
3 No of Storey					
4 Year of Construction					
5 User Department	E	DUCATIONAL INSTITUTE			
6 Mode Of Construction of existing bldg.	OPEN FOUNDATION RCC RCC				
i) Foundation					
ii) Floors					
iii) Walls		BRICK WALLS			
iv) Beams		RCC			
v) Columns		RCC			
vi) Roof		FLAT RCC ROOF			
7 History of Repairs done year -wise-					
(a) Slab recasting		NOT REQUIRED			
(b) Column Jacketing		NOT REQUIRED			
i) Structural Repairs		2010-11			
ii) Tenantable Repairs	AS AND WHEN REQUIRED DONE AS AND WHEN REQUIRED				
iii) Roof /Waterproofing					
iv) Plumbing					
v) Additions/ Alterations if Any		NOT DONE			
8 Date of Inspection by Consultant	26th FEBRUARY 2021				
9 Condition of					
i) Internal plaster	OK PLASTER CRACKS SOME LEAKAGES ARE THERE				
ii) External plaster					
iii) Plumbing					
iv) Drains lines/ chambers		ОК			
.0 a) Doors & windows don't close	DOOR	S AND WINDOWS GET CLOSED			
b) Columns & Steel exposed	COLUMN CRACKED AT SOME LOCATIONS				
c) Settlement uneven flooring gaps between and skirting, floor	NO U	NO UNEVEN SETTELMENT FOUND			
d) Foundation settlement	NO FOUNDATION SETTELMENT OBSERVED				
e) Deflections/ sagging		NO SAGGING AND DEFLECTION MAJOR CRACK IN ONE COLUMN			
f) Major cracks in column/ beams					
g) Seepages/ Leakages	PRE	SENT AT SOME LOCATIONS			
h) Staircase area/ column condition	NO PROBLEM IN THIS AREA				
i) Lifts walls		NO PROBLEM IN THIS AREA NO PROBLEM IN THIS AREA			
j) U.G. Tank					
k) OHT/ Column condition		ACKS IN BOTTOM SLAB/COLUMNS			
I) Parapet at terraces	M	MINOR CRACKS IN PARAPET CRACKS IN CHAJJA OK			
m) Chhajas					
n) Common areas					
o) Toilet blocks		ОК			
p) Terrace Water Proofing	NO MAJOR DEFECT				
Test carrired out on structure/ observations there of	Findings	Range as per IS Code			
NDT a) Ultrasonic pulser velocity Test (m/sec)	2842.45	3500			
b) Rebound Hammer Test (Avg. Rebound value)	27.7	Fair			
c) Half Cell Potential Test (Mv)	-310	50% corrosion			
d) Carbonation Depth Test (mm)	41	10 to 13.5			
	41	10 10 13.3			



V. V. JOSHI AND ASSOCIATES CONSULTING ENGINEERS

5, Ishwar Bhavan, Liberty Garden Cross Road No.2, Malad (West), Mumbai - 400 064. Telefax: 2882 0966 • Email: vvjoshiasso@gmail.com

	f) Chemical Analysis (pH,Cl,SO3)	9.5.0.4.150mg/l	Not Less than 8, <0.6, > 400mg/l	
	g) Cement aggregate ratio		ble as sample cannot be taken	
13	Distress Mapping Plan & Photograph with caption below about			
	description of structural member and its location	ARE	ATTACHED WITH REPORT	
14	Brief Description of repairs to be done	POLYMER MOD	IFIED MORTAR REPAIRS	
-	a) Water proofing		NOT NECESSARY	
	b) External plaster	CRACK FILLING AND PATCH REPAIR		
	c) Structural repairs			
	i) Column jacketing		NOT NECESSARY	
	ii)Slab recasting	NOT NECESSARY		
	iii) RCC cover to be replaced	NECESSARY AT FEW PLACES		
	iv) Beam recasting.	NOT NECESSARY		
	d) Partial Evacuation during repairs needed		NOT NECESSARY	
	e) Propping		NOT NECESSARY	
15	Conclusions Of Consultants	Observa-tions	Key reason	
	i) Whether structure is Livable/ of wheather it is to be evacuated/ pulled Down.	STRUCTURAL IS LIVABLE		
	ii) Whether structure requires tenantable repairs/ major structural repairs & its time frame	REPAIRS REQD	MINOR TENANTABLE REPAIRS	
	iii) Whether Structure can be allowed to occupy during course of repairs	YES		
	iv) Nature/ Methodology of repairs.		APPLY POLYMER MODIFIED MORTAR	
	v)Wheather Structure requires immediate propping if so its propping plan/ methodology given		NO	
	vi) Whether other immediate safety measures required -what is specific recommendation	NIL		
	vii) Enhancement in life of structure after required repairs /frecuency of repairs required in extended life period			
	viii) projected repair cost/sq.ft			
	ix) projected reconstruction cost/sq.ft			
	 x) specific remarks ,wheather building needs to be vacated/ demolished/ repairable. 	No vacating the building during repairs		
	xi) whether structure in exetremely critical condition		CRITICAL CONDITION	
16	Critical Observation			
17	Classification of Bldg.	C3	Auditors Final conslusion	
		C 1	To be evacuated demolition immediately.	
		C2- A	To be evacuated and/or partial demolition requiring strctural repairs	
		С2-В	No eviction only structural repairs	
			Annual Control of the	

Signature

Structural Auditor, V. JOSHI

Consulting Engineer M.C.G.M. Reg. No. STR/J/4